


TYPE 603



TYPE 606

AFTER CLIP ASSEMBLY THE FIRST RIBS MAYBE MISSING OR DEFORMED (TYPE 606 ONLY)

DEFORMATION MAY OCCUR AT END OF CLIP AND AT END OF CONNECTOR CLIP SLOT AFTER ASSEMBLY (ALL TYPES)

- [illegible]

[illegible]