SYMBOL DEFINITION			MISSING SYMBOLS
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL ( ) DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.	TOTAL NO OF INSPECTIONS REQUIRED	91	NO MISSING SYMBOL NUMBER
	LAST NO. USED	55	

DWG STATUS					ZONE	REVISION HISTORY	AUTH	DR	APVD	APVD
DATE	STN	REV	N/P	CHG					I.E.	R.E.
30SE05	R	01	-	-	-	CLEARED REV 01L AND REDRAWN TO PC1 12191935 OBSOLETE	273000	CCV	JAA	MMM



NOTES

1. UNLESS OTHERWISE SPECIFIED AND/OR INDICATED:

   DIMENSIONS ARE TO FACE OF VIEW SHOWN AND AUTOMATICALLY ROUNDED BY COMPUTER FOR INSPECTION (SEE MATH MODEL FOR PRECISE DIMENSIONS). FOR ALL OTHER DIMENSIONS NOT SHOWN BUT REQUIRED FOR TOOL BUILD, SEE MATH MODEL FOR PRECISE TOOL PATH DATA.

2. "O" INDICATES PROCESS SENSITIVE DIMENSION FOR PART PRODUCTION AND ARE TO BE USED FOR INITIAL CAPABILITY STUDY. THESE DIMENSIONS ARE ALSO TO BE MONITORED DURING NORMAL PRODUCTION.

PART NO	REV	N/P	STATUS	TYPE	CAP MATERIAL SPECIFICATION AND COLOR	TERMINAL	CAP	MATING CONNECTOR
15369276	A	-	-	104	R007/754 PA66 HS IM-BLK	12191930	12191929	12191928
15354636	A2	-	-	103	R007/754 PA66 HS IM-BLK	12191930	12191929	12191928
12191935	A4	-	OBSOLETE	102	R007/621 PA66 HS IM-BGE	12191934	12191933	12191932
12191931	B2	-	-	101	R007/754 PA66 HS IM-BLK	12191930	12191929	12191928

(N/A) PROCESS SENSITIVE DIMENSION	
REFERENCE	
DIMENSIONS CONVERTED TO & RELEASE	
ALL DIMENSIONS ARE IN MILLIMETERS	

| DIMENSIONAL RANGE (MM) | | | | |