



















SYMBOL DEFINITION		MISSING SYMBOL
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL (—) DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.	TOTAL NO OF INSPECTIONS REQUIRED: 32	NO MISSING SYMBOL NUMBER
	LAST NO. USED: 24	

| DRAWING HISTORY | | |