

SYMBOL DEFINITION		MISSING NUMBERS
A DIMENSION WITHOUT TOPPAL NO. AN INSPECTION REPORT SYMBOLS 75		77,
DRAWING IS REQUIRED FOR DRAWING		
REQUIRING INSPECTION,		
IT MAY BE CONTROLLED	LAST PRT NO.	96
ON AN INDIVIDUAL COMPONENT DRAWING.	USED	

| REVISION HISTORY | | |