SYMBOL DEFINITION		MISSING SYMBOLS	
A DIMENSIONS WITHOUT ANY INSPECTION REPORT SYMBOL, MUST BE INSPECTED ACCORDING TO THE SAME CONTROLLING ON THE TRADITIONAL COMPONENT DRAWING.	TOTAL NO. OF DIMENSIONS REQUIRED: 25	NO MISSING SYMBOLS. TOTAL NO. OF MISSING SYMBOLS: 0	
	LAST NO. USED: 25		