| SYMBOL DEFINITION | | MISSING SYMBOLS, NO MISSING SYMBOL NUMBER |
|---|---|---|
| A. DIMENSIONS WITHOUT AN INSPECTION REPORT SYMBOL, THAT DOES NOT REQUIRE INSPECTION, IS NOT BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWINGS. | TOTAL NO OF INSPECTIONS REQUIRED | 17 |
| | LAST NO. USED | 17 |

| REVISION HISTORY | | |