

[illegible]

	7	6	5
SYMBOL DEFINITION			
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL (I) DOES NOT REQUIRE INSPECTION, IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.	TOTAL NO OF INSPECTIONS REQUIRED		4
	LAST NO. USED		2

MISSING SYMBOLS		REVISED HISTORY		DATE	ON	OFF
NO MISSING SYMBOL NUMBER	10	10	10	10	10	10
10	10	10	10	10	10	10
10	10	10	10	10	10	10

[illegible][illegible]

2339398