SYMBOL DEFINITION	SYMBOL DEFINITION	MISSING SYMBOLS
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL (*) DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.	TOTAL NO OF INSPECTIONS REQUIRED 36	NO MISSING SYMBOL NUMBER
	LAST NO. USED 25	

| REVISION HISTORY | | |