SYMBOL DEFINITION		MISSING SYMBOLS
X DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL (*) DOES NOT REQUIRE INSPECTION, IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.	TOTAL NO OF INSPECTIONS REQUIRED: 45	NO MISSING SYMBOLS
	LAST NO. USED: 20	

| ENG STATUS | | |