




TYPE 102
SAME AS TYPE 101
EXCEPT AS SHOWN




TYPE 103
SAME AS TYPE 101
EXCEPT AS SHOWN




TYPE 104
SAME AS TYPE 101
EXCEPT AS SHOWN




TYPE 105
SAME AS TYPE 101
EXCEPT AS SHOWN





TYPE 106
SAME AS TYPE 103
EXCEPT AS SHOWN







TYPE 101









SYMBOL DEFINITION		
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL (-) DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.	TOTAL NO OF INSPECTIONS REQUIRED	13
	LAST NO. USED	13

MISSING SYMBOLS
NO MISSING SYMBOL NUMBER

| REVISION HISTORY | | |