

MATING SHROUD AND BLADE REQUIREMENTS

DIMENSIONS SHOWN ARE FOR TYPE 101

TYPE 102

SAME AS TYPE 101 EXCEPT AS SHOWN

TYPE 103

SAME AS TYPE 101 EXCEPT AS SHOWN

SYMBOL DEFINITION		MISSING SYMBOLS
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL (..) DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.	TOTAL NO OF INSPECTIONS REQUIRED: 7	NO MISSING SYMBOL NUMBER
	LAND NO. USED: 7	

| REVISION HISTORY | | |