



W02 Assembling Steps



No	Quantity	No	Quantity	Hardware
①	2Pcs	A	4Pcs	
②	2Pcs	B	4Pcs	
③	2Pcs	C	1Pcs	
④	1Pcs	D	1Pcs	
⑤	1Pcs	E	2Pcs	
⑥	1Pcs	F	2Pcs	
⑦	1Pcs	G	2Pcs	
⑧	1Pcs	H	1Pcs	
⑨	2Pcs	I	1Pcs	
⑩	1Pcs			