

Wiper Blade Change

SAM 3051

Current



New

Current



New



ENGINEERING CHANGE NOTICE

Manufacturing location and packaging change. This can be referenced by the photographs shown above. This change does not affect product performance. Mixed shipments are possible. Affected Product Code & Starting Lot Numbers below:

| Affected Product Code | Starting Lot Code |
|-----------------------|-------------------|
| SAM3051WBLD-10 | 20062024-1 |