

Engineering Change to Replacement Wiper & Doctor Blade

Current



New



Lot number



Current



New



Lot number



There is an engineering change to our Wiper and Doctor Blade. The new part has Zinc stamping and the lot number is either engraved or printed on the stamping

This change can be referenced by the photographs shown above (representative).
Mixed shipments are possible.

Please refer to the following table for Affected Product Codes & respective Starting Lot Codes

Affected Product Code	Starting Lot Code
PXWBLD-10	QHAB
LT640WBLD-10	OKMB/OL4B/OLGB/OK7B/PLXB/PGPB/PGKB
SAM1610WBLD-10	QFFB
SAM205WBLD-10	PFAB
H4350WBLD-10	PGKB
X4510WBLD-10	PXXB
SAM105WBLD-10	PJFB
H4515DBLD-10	OKMB/OL6B/OJDB/OKLB/OKAB
LT650WBLD-5	OJXB
AXDBLD-10	PFDB
AXWBLD-5	PEWB
SAM506BLADE-10	PG5B
H5525WBLD-10	PFDB
H1012DBLD-10	OLOD
H1505DBLD-10	OGA1/QIL1
HP1505BLADE2-10	DJ112/DIH32/QJH12
H1012WBLD2-10	ZIJQ
HP2025DBLADE-5	OLH2/OLD1
HP2055DBLADE-10	OF828/OF718

Affected Product Code	Starting Lot Code
HP2055WBLD-10	7110
H2300WBLD-10	QL11
4KDBLD-10	RF21
HM506DBLD-20	RER1
H2300DBLD-10	PFDB
HP43DBLADE-3-10	OLQB
5KWBLD-10	PA4B
H5200DBLD-10	OLNB/OLMB
9KDBLADE-2	PEQB
HM402WBLD-10	QKU1
HM252WBLD-10	OKC2
H3525WBLD-10	RJB3
SAM2851WBLD-10	PBNB
SAM103WBLD-10	PFDB
SAM3051WBLD-10	PH5B
H1025WBLD-10	TG71