

Current

ENGINEERING CHANGE NOTICE

Doctor Blade Change B2240




New

Intl: +1.919.774.3808 | US, Toll-Free: 1.800.488.2426 | email: info@scc-inc.com | web: www.scc-inc.com



ENGINEERING CHANGE NOTICE



Manufacturing location and packaging change. This can be referenced by the photographs shown above. This change does not affect product performance. Mixed shipments are possible. Affected Product Code & Starting Lot Numbers below:

Affected Product Code	Starting Lot Code
B2240DBLD-10	29042024-1

Intl: +1.919.774.3808 | US, Toll-Free: 1.800.488.2426 | email: info@scc-inc.com | web: www.scc-inc.com