


Doctor Blade Change

HP 2300


New

Current




New

Current



New

Current



Manufacturing location change. This can be referenced by the photographs shown above. This change does not affect product performance. Mixed shipments are possible. Affected Product Code & Starting Lot Numbers below:

Affected Product Code	Starting Lot Code
H2300DBLD-10	11082023-1