

ENGINEERING CHANGE NOTICE

Doctor Blade Change

HP P1505



Intl: +1.919.774.3808 | US, Toll-Free: 1.800.488.2426 | email: info@scc-inc.com | web: www.scc-inc.com



Static Control[®] ENGINEERING CHANGE NOTICE



Intl: +1.919.774.3808 | US, Toll-Free: 1.800.488.2426 | email: info@scc-inc.com | web: www.scc-inc.com



Static Control[®] ENGINEERING CHANGE NOTICE



Manufacturing location change. New Doctor Blade has foam backing. This can be referenced by the photographs shown above. This change does not affect product performance. Mixed shipments are possible. Affected Product Code & Starting Lot Numbers below:

Affected Product Code	Starting Lot Code
H1505DBLD-10	11082023-1

Intl: +1.919.774.3808 | US, Toll-Free: 1.800.488.2426 | email: info@scc-inc.com | web: www.scc-inc.com