

## Redesigned HP®/Canon® End Plates Create Performance Issues

### New Cartridge Lubricant Recommended

We have discovered that many of the newest generation of HP®/Canon® end plates have been designed with drum hubs that have slightly flattened sides. In the past, round hubs were the standard.



**OLD Generation**



**NEW Generation**

By redesigning the shape of the hub, these new end plates generate more friction which can cause issues such as noise, material transfer and seizing.



Using our new **multi-purpose cartridge lubricant (LUBE44)** eliminates these issues.

**Static Control will ONLY sell to genuine cartridge remanufacturers.  
We will not sell to manufacturers of new build/clone ink and laser cartridges.**

Intl: +1.919.774.3808 | US, Toll-Free: 1.800.488.2426 | email: [info@scc-inc.com](mailto:info@scc-inc.com) | web: [www.scc-inc.com](http://www.scc-inc.com)

© Static Control Components, Inc. All rights reserved worldwide. The stylized S, Static Control and Odyssey are registered trademarks of Static Control Components, Inc. All other brand or product names are trademarks or registered trademarks of their respective companies.

If you do not wish to receive our updates, please reply to this email with 'Unsubscribe' in the subject line.  
(EB #001209\_us)