

Wiper Blade Change

HP CP5525

Current



New

Current



New

Current



New

Manufacturing location change. This can be referenced by the photographs shown above. This change does not affect product performance. Mixed shipments are possible. Affected Product Code & Starting Lot Numbers below:

Affected Product Code	Starting Lot Code
H5525WBLD-10	20062024-1