


Wiper Blade Change


HP P1505





New

Current



Manufacturing location change. New Doctor Blade has glued type urethane. This can be referenced by the photographs shown above. This change does not affect product performance. Mixed shipments are possible. Affected Product Code & Starting Lot Numbers below:

Affected Product Code	Starting Lot Code
HP1505BLADE2-10	11082023-1