

HP® LaserJet® P4515/M4555/M630 Family Conversion Chart

NOTE: The OEM drum shutter assembly, torsion spring and gearing will need to be reused from the cartridge being converted.
 The HM630WBIN can be used as an alternative to modifying the OEM waste bin for the M630 conversions.

KEY		CONVERTING TO						
		Chipped Cartridges (Install New Correct Chip)						
		CC364A HP® LaserJet® P4014/4015/4515 10,000 pages	CC364X HP® LaserJet® P4015/P4515 24,000 pages	CE390A HP® LaserJet® Enterprise® M4555 MFP/M600 10,000 pages	CE390X HP® LaserJet® Enterprise® M4555 MFP/M600 24,000 pages	CF281A HP® LaserJet® Enterprise® M630 MFP 10,500 pages	CF281X HP® LaserJet® Enterprise® M630 MFP 25,000 pages	
CONVERTING FROM	Chipped Cartridges (Install New Correct Chip)	CC364A HP® LaserJet® P4014/4015/4515 10,000 pages	Straight Remanufacture	N/A	▶ HP4515WBIN	N/A	▶ HM630DBPLT * ■ HM630DSECAP # HM630CSECAP	N/A
	CC364X HP® LaserJet® P4015/P4515 24,000 pages	▶ Install New Correct Chip (U24CHIP-10) <i>(CC364X not accepted by P4014 printer)</i>	Straight Remanufacture	▶ HP4515WBIN	▶ HP4515WBIN	▶ HM630DBPLT * ■ HM630DSECAP # HM630CSECAP	▶ HM630DBPLT * ■ HM630DSECAP # HM630CSECAP	
	CE390A HP® LaserJet® Enterprise® M4555 MFP/M600 10,000 pages	▶ HP4515WBIN	N/A	Straight Remanufacture	N/A	▶ HM630DBPLT * ■ HM630DSECAP # HM630CSECAP	N/A	
	CE390X HP® LaserJet® Enterprise® M4555 MFP/M600 24,000 pages	▶ HP4515WBIN <i>(CE390X not accepted by P4014 printer)</i>	▶ HP4515WBIN	▶ Install New Correct Chip (U35-2CHIP-10)	Straight Remanufacture	▶ HM630DBPLT * ■ HM630DSECAP # HM630CSECAP	▶ HM630DBPLT * ■ HM630DSECAP # HM630CSECAP	
	CF281A HP® LaserJet® Enterprise® M630 MFP 10,500 pages	N/A	N/A	N/A	N/A	Straight Remanufacture	N/A	
	CF281X HP® LaserJet® Enterprise® M630 MFP 25,000 pages	N/A	N/A	N/A	N/A	▶ Install New Correct Chip (H630CP-10)	Straight Remanufacture	

* To complete the conversion, this requires additional modification (trimming) to the OEM waste bin.