




HOW TO USE IT?



Range: 1.5 Nm - 30 Nm



- Adaptor: 1/4" M x 3/8" F
- Socket: 1/4" Drive x 11mm
- Accuracy: $\pm 1\%$
- Indicator: 4 Digits (update rate of 5 per second)
- Temp. Range-Operating: $+5^{\circ}\text{C}$ to $+40^{\circ}\text{C}$
- Temp. Range-Storage: -20°C to $+70^{\circ}\text{C}$
- Auto Reset Hold Time: 2 Seconds
- Calibration: According to BS7882:2017 method
- Sampling rate: 333SPS
- Directions: C.W.

Check your parts**Function**

- ① 11mm (Drive End)
- ② 5 Digits Display
- ③ 4 Holes $\Phi 10$
- ④ Power switch
- ⑤ DC Input (9V 1.6A)
- ⑥ Zero Key

Position**Timing**

Installation

