


SYMBOL DEFINITION				MISSING SYMBOLS		DWG STATUS		ZONE	REVISION HISTORY	AUTH	DR	APVD 1	APVD 2				
				DATE	STG	REV	N/P							CHG			
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL  DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.		TOTAL NO OF INSPECTIONS REQUIRED	11	NO MISSING SYMBOL NUMBER		18JA05	R	01	-	-		CREATED PD		263490	RH	RH	BG
						18FE09	R	02	-	-		ALL PARTS - ADDED APPLICATION DATA NOTE		407218	MGE	ECB	MGE
						17AP19	R	03	-	-		ALL PARTS - PSD WAS "5"		442966	GDH	JAA	CFH
		LAST NO. USED	11														