

SYMBOL DEFINITION

SYMBOL	DEFINITION	TOTAL NO. OF INSPECTIONS REQUIRED	LAST NO. USED
A	A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.	4	5

MISSING SYMBOLS

DATE	STATUS	ZONE	REVISION HISTORY	AUTH	DR	APPROVED
25/03/03	R	01	-	-	-	-
26/03/03	R	02	-	-	-	-
11/04/04	R	03	-	-	-	-
11/04/04	R	04	-	-	-	-
16/04/04	R	04	-	-	-	-

DELPHI
DELPHI PACKARD ELECTRIC SYSTEMS
MIRAL, OH

NOTES

- UNLESS OTHERWISE SPECIFIED AND/OR INDICATED: DIMENSIONS ARE TO FACE OF VIEW SHOWN AND AUTOMATICALLY ROUNDED BY COMPUTER FOR INSPECTION (SEE MATH MODEL FOR PRECISE DIMENSIONS). FOR ALL OTHER DIMENSIONS NOT SHOWN BUT REQUIRED FOR TOOL BUILD, SEE MATH MODEL FOR PRECISE TOOL PATH DATA.
- MATERIAL RECYCLING CODE PER ISO 11469. (1.5)X(0.1) CHARACTERS AS SHOWN TO BE LOCATED ON ANY EXTERIOR SURFACE.
- MATING COMPONENTS OR EQUIVALENT: CONNECTOR 15467560
- INSERTION FORCE WITH MATING CONNECTOR SHALL BE BETWEEN 15 AND 65 NEWTONS.
- EXTRACTION FORCE FROM MATING CONNECTOR SHALL BE BETWEEN 15 AND 100 NEWTONS.

PROCESS SENSITIVE DIMENSION

THIRD ANGLE PROJECTION

USE MATH DATA

LOCK TPA COMB

15467562