

DWG STATUS

DATE STG REV N/P CHG

DATE STOREVINOPICHO

MISSING SYMBOLS

NO MISSING


SYMBOL NUMBER

SYMBOL DEFINITION


A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL


DOES NOT REQUIRE INSPECTION. IT MAY BE
CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.


TOTAL NO OF
INSPECTIONS
REQUIRED





SAME AS TYPE 101 EXCEPT AS SHOWN














A1×3 2:1 2 0F 2 1 0F 1 R 02 -

 
 35312616
 01
 AA
 103
 35312615
 35197125

 35197171
 01
 AA
 102
 35197174
 35197125

 35197170
 01
 AA
 101
 35197173
 35197125
 PART NO REV N/P TYPE CONN PLR

N/A PROCESS SENSITIVE DIMENSION REFERENCE DIMENSIONS ENCLOSED IN ( ) INDICATE
REFERENCE DIMENSIONS AND NO TOLERANCE
LIMITS ARE ESTABLISHED