

76647 Test Strip 4 in 1 – Total Bromine



Total Bromine / pH / Total Alkalinity /
Total Hardness

INSTRUCTIONS FOR USE

01/ REMOVE

With dry hands, open the cap and remove a test strip.

02/ DIP

For best results, use test strip away from skimmers or returns. Dip strip at wrist depth and remove with pads facing up.

DO NOT shake off excess water. Hold strip level for 20 SECONDS.

03/ READ

Compare to colour chart. Read in order: Br→ pH→TA →TH

MEASURING RANGE

Total Bromine (Br) ppm: 0, 1, 2, 4, 10 ,20 (recommended: 1 -4)

pH: 6.4, 6.8, 7.2, 7.5, 7.8, 8.4 (recommended: 7.2-7.5)

Total Alkalinity (TA) ppm: 0, 40, 80, 120, 180, 240 (recommended: 80-120)

Total Hardness (TH) ppm: 0,100,150,300,800 (recommended: 150-300)

See label for colour chart.

CONTENT

50 test strips.

ctx
pro

The caring formula

ctxprofessional.com

NOTES

Test water should be within IDEAL range listed on back of bottle. Keep cap closed after removing a strip to prevent moisture from entering the bottle. TEST TWICE WEEKLY. STORE AT ROOM TEMPERATURE

ctx[®]
pro

The caring formula

ctxprofessional.com