

PRODUCT DISCONTINUATION NOTICE

ADLP – Inset Runway and Taxiway Low Profile

- DRC-LP L-850A(L)
- DTZ-LP L-850B(L)
- ITCL-L (D2X) L-852A-D/J/K(L)
- ISTB-L (D2S) L-852S(L)
- DCT, DFS-B Canadian Series



Reference: LGT-L.INST.DRC, DTZ, ITCF, Date: 22-November-2022

ITCF-C, ISTB.

Product Discontinuation Notice

Dear Valued Customer,

This notice is to inform you that ADB SAFEGATE will discontinue the manufacturing of the **ADLP family of low-profile Runway and Taxiway inset lights.**

In accordance with ADB SAFEGATE product discontinuation policy, we are hereby giving notice of these changes so that our customers can adjust their product part number purchasing records or make any final lifetime purchases of discontinued product(s) to support their operations.

In this notice you can find necessary details about the discontinuation target dates, successor product replacement, spare parts policy and last time buy conditions.

We regret the inconvenience and impact this notice may cause. ADB SAFEGATE Sales Representatives stand ready to answer any questions you may have or assist you with any final orders.

ADB SAFEGATE Bill Weigel Product Management Team













Reference: LGT-L.INST.DRC, DTZ, ITCF, Date: 22-November-2022

ITCF-C, ISTB.

Discontinuation Planning

	<u></u>
Product Name	DRC-LP L-850A(L) 8-inch and 12-inch Inset Runway Centerline Light. TDZ- LP L-850B(L) 8-inch and 12-inch Inset Runway Touchdown Zone Light. ITCL-LP (D2X) L-852A-D, J, K(L) 8-inch and 12-inch Inset Taxiway Centerline Light. ISTB-L (D2S) L-852S(L) 8-inch and 12-inch Inset Stop Bar Light. DCT Canadian Taxiway Centerline Curved Section. DFS-B Canadian Taxiway Centerline Straight Section.
Reason(s) for	Does not comply with Engineering Brief 67D - 25% Failed LED Monitored.
Discontinuance	FAA certification expired July 2022.
Last time buy deadline	22 November 2024
	Last day to order complete products.
	Orders for discontinued products will not be accepted after this date.
End-of-Support deadline	22 November 2027
	Spare parts will no longer be available for warranty or non-warranty support, and technical support will be limited to fee-based repair work.

Replacement Product

Discontinued Part Numbers	Replacement Part Number
DRCXXXXXXXXXXX Series	RSRCXXXXXXXXXX1
	AXON Runway Centerline
DTZXXXXXXXXXXXX Series	RSRZXXXXXXXXXX1
	AXON Runway Touchdown Zone
D2XXXXXXXXXXXX Series	RSTXXXXXXXXXXX1
	AXON Taxiway Centerline FAA
	AXON Taxiway Centerline ICAO
D2SXXXXXXXXXXXX Series	RSSBXXXXXXXXXX1
	AXON Stop Bar FAA
	AXON Stop Bar ICAO
TP-312 Canadian Series	
DCTXXXXXXXXXXX	RSTKXXXXXXXXXX1
DFSXXXXXXXXXXX	RSTCXXXXXXXXXX1
TP-312 Canadian Series	AXON Taxiway Centerline ICAO











Reference: LGT-L.INST.DRC, DTZ, ITCF, Date: 22-November-2022

ITCF-C, ISTB.

Spare Parts Availability

The table below shows spare parts that were available for the ADLP fixtures affected by this notice. The rows in red will become obsolete on the End-of-Support deadline indicated above. The rows in green indicate parts that may remain available due to use in other product families. Spare parts are subject to availability.

*See Appendix A for assembly codifications.

Spare Part No	Description	Notes
44A7479/XXXX Series*	LED Optical Assembly	Spare no longer available after
		End of Support Deadline
44A7493/XXXX Series*	Bottom Pan Assembly	Spare no longer available after
		End of Support Deadline
6241222	Optical Assembly Gasket	Spare no longer available after
63A1232		End of Support Deadline
73A0183/10	Jacketed Style 1 Cordset, 18-inch	Spare no longer available after
73A0103/10		End of Support Deadline
4072.24.951	Style 6 Cordset, 2-wire, 10-inch	Spare no longer available after
4072.24.331		End of Support Deadline
4072.24.730	German Style 1 Cordset/Nameplate	Spare no longer available after
		End of Support Deadline
4072.24.770	French 3-pole Cordset	Spare no longer available after
	'	End of Support Deadline
4072.42.350	Style 6 Cordset, 2-wire, 18-inch	Spare no longer available after
		End of Support Deadline
MS00001-255-01	O-Ring, Bottom Pan	Spare no longer available after
	Prism, Standard	End of Support Deadline
63A1226/1		Spare no longer available after End of Support Deadline
	Prism, Sapphire Coating	Spare no longer available after
63A1226/2		End of Support Deadline
	Prism Bracket	Spare no longer available after
60A4520/1		End of Support Deadline
	Prism Protector	Spare no longer available after
63A1238/1		End of Support Deadline
63.44000	Sock Seal, Prism Gasket	Spare no longer available after
63A1228		End of Support Deadline
44A7474	Arctic Kit	Spare no longer available after
44A/4/4		End of Support Deadline
7080.90.740	O-Ring for use in Thorn Shallow Base	Spare no longer available after
7000.30.740	Mount Application	End of Support Deadline
15A0209	Fuse, Fail Open, for Monitored	Spare will remain available after
.57.0205	Converters	End of Support Deadline
65A0550	Spring Pin	Spare will remain available after
		End of Support Deadline
4072.24.781	Labyrinth Gasket for 8" Fixture	Spare will remain available after
		End of Support Deadline











Reference: LGT-L.INST.DRC, DTZ, ITCF,

Date: 22-November-2022

ITCF-C, ISTB.

MF00090-000-01	Pressure Release Screw	Spare will remain available after End of Support Deadline
MS00001-008-01	O-Ring, Pressure Release Screw	Spare will remain available after
		End of Support Deadline
72A0401	Ground Lug	Spare will remain available after
72A0401		End of Support Deadline
60A4537	Cable Clamp, FAA Jacketed	Spare will remain available after
00A4337		End of Support Deadline
4072.42.380	Cable Clamp, Non-Jacketed	Spare will remain available after
4072.42.300		End of Support Deadline
4406104/0	Pressure Test Fitting	Spare will remain available after
44A6104/A		End of Support Deadline

Last-Time Buy Conditions:

- All purchase orders for last -time buys are non-cancellable and non-returnable.
- For orders for only spare parts, a \$150 order minimum is required.
- Leadtime of the spare parts will be confirmed upon order confirmation
- During the final stage of a Spare Part Supply phase ADB Safegate can no longer guarantee full support for the affected products. Spare parts are provided depending on the available inventory; repair and replacement services also depend on component availability.












ITCF-C, ISTB.

Appendix A:

Bottom Pan Assembly



LED Optical Assembly

