

## Product Discontinuation Notice

Dear Valued Customer,

This notice is to inform you that ADB will discontinue the manufacturing of the **FAA L-858 Fluorescent Airfield Guidance Signs, including the Fluorescent High Wind Option** listed in the "Product Transition Table" below.

In accordance with ADB product discontinuation policy, we are hereby giving notice of these changes so that our customers can adjust their product part number purchasing records, or make any final lifetime purchases of discontinued product(s) to support their operations.

Product Transition Table	
Product Name	FAA L-858 Fluorescent Airfield Guidance Sign
Reason(s) for Discontinuance	Little-to-no demand because FAA has not allowed certification of L-858 signs using fluorescent lamps since Nov. 15, 2013.
Last time buy deadline	<b>June 30, 2016</b>
	Last day to order complete products. Orders for discontinued products will not be accepted after this date.
End-of-Support deadline	<b>September 30, 2016</b>
	Spare parts will no longer be available for warranty or non-warranty support, and technical support will be limited to fee-based repair work. Note: Legend Panels (44A6084-XXXX) and the Legend Panel Divider Assembly 44A6173-XXX) are the same as used in LED and incandescent signs that will remain available. Therefore, panel and divider replacements will still be available.

Equivalent product replacements are available for this product as indicated in the "Product Replacement Table" below.

Product Replacement Table	
Discontinued Part Number	Replacement Part Number
FAA L-858 “SFX-XXXXXXX” Fluorescent Series and “SNX-XXXXXXX” High Wind Fluorescent Series	SR or SS (High Wind) series FAA L-858 LED Airfield Guidance Sign. Information is at: <a href="http://www.adb-air.com/products-solutions/product-center/product/led-airfield-guidance-sign-faa.aspx">http://www.adb-air.com/products-solutions/product-center/product/led-airfield-guidance-sign-faa.aspx</a>  FAA LED Airfield Guidance Sign retrofit kit. Service Bulletin ALN158 is at: <a href="http://www.adb-air.com/media/Documents/1537/ALN158-Incandescent-or-Fluorescent-to-LED-Light-Bar-Sign-Kits-94A0628-XXX.pdf">http://www.adb-air.com/media/Documents/1537/ALN158-Incandescent-or-Fluorescent-to-LED-Light-Bar-Sign-Kits-94A0628-XXX.pdf</a>

### Spare Parts:

The table below shows spare parts that were available for the L-858 Fluorescent Airfield Guidance Sign. Most of the parts in the fluorescent sign are common with other signs that will remain active. The rows in red will be made obsolete on the schedule indicated above.

#### Phase-out Spare Parts – Fluorescent Sign

Part No	Description	Notes
35A0687-1	Fluorescent sign ballast, one-lamp	
35A0687-2	Fluorescent sign ballast, two-lamp	
60A2953	Fluorescent sign optical bracket	
44A6631	Fluorescent sign power supply	
48A0376	Fluorescent Lamp, 18 W	

### Last-time buy Conditions:

- All purchase orders for last -time buys are non-cancellable and non-returnable.
- For orders for only spare parts, a \$150 order minimum is required.
- For orders which include complete signs, a \$2,000 order minimum is required.

We regret the inconvenience and impact this notice may cause. ADB Sales Representatives stand ready to answer any questions you may have or assist you with any final orders.