



ADB SAFEGATE

## Last Time Buy

IRCL-L L-850A(L) LED Inset Runway Centerline Light  
TDZL-L L-850B(L) LED Inset Runway Touchdown

  
**ADB  
SAFEGATE**

## Last Time Buy Notice

*Dear Valued Customer,*

*This notice is to inform you that ADB SAFEGATE will discontinue the manufacturing of the **IRCL-L and TDZL-L family of LED in-pavement Runway Centerline and Runway Touchdown Zone lights.***

*In accordance with ADB SAFEGATE product discontinuation policy, we are hereby giving notice of these changes so that our customers can adjust their product part number purchasing records or make any final lifetime purchases of discontinued product(s) to support their operations.*

*In this notice you can find necessary details about the discontinuation target dates, successor product replacement, spare parts policy and last time buy conditions.*

*We regret the inconvenience and impact this notice may cause. ADB SAFEGATE Sales Representatives stand ready to answer any questions you may have or assist you with any final orders.*

*ADB SAFEGATE  
Bill Weigel  
Product Management Team*



## Discontinuation Planning

<b>Product Name</b>	IRCL-L LED In-pavement Runway Centerline Light. TDZL-L LED In-pavement Runway Touchdown Zone Light.
<b>Reason(s) for Discontinuance</b>	Does not comply with Engineering Brief 67D - 25% Failed LED Monitored. FAA certification expired January 2017. Original PDN issued July 2018 with LTB January 1, 2019.
<b>Last time buy deadline</b>	<b>22 May 2023</b> Last day to order complete products. Orders for discontinued products will not be accepted after this date.
<b>End-of-Support deadline</b>	<b>1 January 2024 (Original commitment date from July 2018 PDN)</b> Complete fixtures and spare parts will no longer be available for non-warranty support, and technical support will be limited to fee-based repair work. Warranty support will continue until the 4-year obligation is completed, based on date of sale.

## Replacement Product

Discontinued Part Numbers	Replacement Part Number
IRCL/XXXXXX Series	RSRC1XXXXXXXXXX1 <a href="#">AXON LED Runway Centerline Light</a>
TDZL/XXXXXX Series	RSRZ1XXXXXXXXXX1 <a href="#">AXON Runway Touchdown Zone Light</a>

## Spare Parts Availability

The table below shows spare parts that were available for the IRCL/TDZL-L fixtures affected by this notice. The rows in orange will become obsolete on the End-of-Support deadline indicated above. The rows in green indicate parts that may remain available due to use in other product families. Spare parts are subject to availability.

Spare Part No	Description	Notes
44A7257/1	PCB PS ASSY, L850/L852D, 600mA, 6 LED's	Spare no longer available after End of Support Deadline
44A7257/2	PCB PS ASSY, L850/L852D, 600mA, 3 LED's	Spare no longer available after End of Support Deadline
44A7257/3	PCB PS ASSY, L850/L852D, 640mA,	Spare no longer available after End of Support Deadline
44A7257/4	PCB PS ASSY, L850/L852D, 640mA, 8 LED's	Spare no longer available after End of Support Deadline
44A7257/5	PCB PS ASSY, L850/L852D, 640mA, 10 LED's	Spare no longer available after End of Support Deadline
44A7223/11201	INTERM. PAN ASSY,1CD,50/60HZ,DUAL DR,NM	Spare no longer available after End of Support Deadline
44A7223/21101	INTERM. PAN ASSY,2CD,50/60HZ,SNGL DR,N/M	Spare no longer available after End of Support Deadline
44A7223/11101	INTERM. PAN ASSY,1CD,50/60HZ,SNGL DR,N/M	Spare no longer available after End of Support Deadline
44A6975/110	BOT CVR ASSY CURR 6 LED 600ma STL 6 CORD	Spare no longer available after End of Support Deadline
44A6975/210	BOT CVR ASSY CURR 3 LED 600ma STL 6 CORD	Spare no longer available after End of Support Deadline
44A6975/310	BOT CVR ASSY CURR 5 LED 600ma STL 6 CORD	Spare no longer available after End of Support Deadline
44A6975/410	BOT CVR ASSY CURR 8 LED 600ma STL 6 CORD	Spare no longer available after End of Support Deadline
44A6975/510	BOT CVR ASSY CURR 10 LED 600ma STL6 CORD	Spare no longer available after End of Support Deadline
48A0419/RED	IRCL FAA LIGHT ENGINE, RED	Spare no longer available after End of Support Deadline
48A0419/WHT	IRCL FAA LIGHT ENGINE, WHT	Spare no longer available after End of Support Deadline
63A1119/1	IRCL/TDZL PRISM	Spare no longer available after End of Support Deadline
63A1120	PRISM SEAL IRCL	Spare no longer available after End of Support Deadline
61A0444	IRCL PRISM SOCK SEAL	Spare no longer available after End of Support Deadline
60A4046	PRISM CLAMP IRCL	Spare no longer available after End of Support Deadline

60A4047	PRISM KEEPER PLATE IRCL	Spare no longer available after End of Support Deadline
61A0459	HEATER DISC, 2 LEADS W/Terminals	Spare will remain available after End of Support Deadline
4071.50.090	INNER PAN CABLE CLAMP	Spare will remain available after End of Support Deadline
4072.42.351	CORD 2 CONDUCTOR 18	Spare will remain available after End of Support Deadline
4072.42.380	CORD CABLE CLAMP	Spare will remain available after End of Support Deadline
44A7387/10	F-RANGE CORD SET OVERMOLD STYLE 1	Spare will remain available after End of Support Deadline
60A3339/1	44A7767 1 CORD W/O MONITORING	Spare will remain available after End of Support Deadline
60A4153/10	PWR SUPPLY MTG BRKT L-861 INSET 3/8	Spare will remain available after End of Support Deadline
60A2602	PRESSURE RELIEF SCREW	Spare will remain available after End of Support Deadline
63B0267/011	O-RING, PRESSURE RELEASE SCREW	Spare will remain available after End of Support Deadline
63A1285	O-RING, INNER COVER SEAL	Spare will remain available after End of Support Deadline
MS00001-376-01	O-RING, TOP INNER COVER	Spare will remain available after End of Support Deadline
72A0401	ALUM GRND LUG, FOR AL/CU & UL467	Spare will remain available after End of Support Deadline
70A0329	FEM DISC 16-14AWG .25X.03 INS	Spare will remain available after End of Support Deadline

### Last-Time Buy Conditions:

- All purchase orders for last -time buys are non-cancellable and non-returnable.
- For orders for only spare parts, a \$150 order minimum is required.
- Leadtime of the spare parts will be confirmed upon order confirmation
- During the final stage of a Spare Part Supply phase ADB Safegate can no longer guarantee full support for the affected products. Spare parts are provided depending on the available inventory; repair and replacement services also depend on component availability.