



ADB SAFEGATE

PRODUCT DISCONTINUATION NOTICE

ITCF-L – LED Inset Taxiway Centerline Light

- L-852A(L) Category I/II Narrow Beam, $\geq 1,200$ ft RVR
- L-852B(L) Category I/II Wide Beam, $\geq 1,200$ ft RVR
- L-852C(L) Category III Narrow Beam, $< 1,200$ ft RVR
- L-852D(L) Category III Wide Beam, $< 1,200$ ft RVR
- L-852J(L) Category I/II Curved Beam, $\geq 1,200$ ft RVR
- L-852K(L) Category III Curved Beam, $< 1,200$ ft RVR


**ADB
SAFEGATE**

Product Discontinuation Notice

Dear Valued Customer,

*This notice is to inform you that ADB SAFEGATE will discontinue the manufacturing of the **ITCF-L family of LED in-pavement Taxiway Centerline lights.***

In accordance with ADB SAFEGATE product discontinuation policy, we are hereby giving notice of these changes so that our customers can adjust their product part number purchasing records or make any final lifetime purchases of discontinued product(s) to support their operations.

In this notice you can find necessary details about the discontinuation target dates, successor product replacement, spare parts policy and last time buy conditions.

We regret the inconvenience and impact this notice may cause. ADB SAFEGATE Sales Representatives stand ready to answer any questions you may have or assist you with any final orders.

*ADB SAFEGATE
Bill Weigel
Product Management Team*



Discontinuation Planning

| | |
|-------------------------------------|--|
| Product Name | ITCF-L FAA LED In-pavement Taxiway Centerline Light. |
| Reason(s) for Discontinuance | No longer FAA certified. Does not comply with Engineering Brief 67D for failed LED monitoring. |
| Last time buy deadline | 22 November 2023 Does not comply with Engineering Brief 67D - 25% Failed LED Monitored. FAA certification expired October 2021. |
| End-of-Support deadline | 22 November 2027 Spare parts will no longer be available for warranty or non-warranty support, and technical support will be limited to fee-based repair work. |

Replacement Product

| Discontinued Part Numbers | Replacement Part Number |
|---------------------------|---|
| ITCF/AX0XXX Series | RSTA2XXXXXXXXXX1 |
| ITCF/BX0XXX Series | RSTB2XXXXXXXXXX1 |
| ITCF/CX0XXX Series | RSTC2XXXXXXXXXX1 |
| ITCF/DX0XXX Series | RSTD2XXXXXXXXXX1 |
| ITCF/JX0XXX Series | RSTJ2XXXXXXXXXX1 |
| ITCF/KX0XXX Series | RSTK2XXXXXXXXXX1 |
| | AXON FAA Taxiway Centerline |

Spare Parts Availability

The table below shows spare parts that were available for the ITCF-L fixtures affected by this notice. The rows in red will become obsolete on the End-of-Support deadline indicated above. The rows in green indicate parts that may remain available due to use in other product families. Spare parts are subject to availability.

*See Appendix A for assembly codifications.

| Spare Part No | Description | Notes |
|--------------------|---|---|
| *44A6759/XXXXX1 | BOTTOM PAN ASSEMBLY | Spare no longer available after End of Support Deadline |
| *48A0443/XXX/XXXXX | LED LIGHT ENGINE | Spare no longer available after End of Support Deadline |
| *48A0444/XXX/XXXXX | LED LIGHT ENGINE | Spare no longer available after End of Support Deadline |
| 63A0979/3 | PRISM L-852A(L), B(L) and J(L) | Spare will remain available after End of Support Deadline |
| 63A0993/2 | PRISM, L-852C(L), D(L) and K(L) | Spare will remain available after End of Support Deadline |
| 4071.50.030 | PRISM GASKET SLEEVE | Spare will remain available after End of Support Deadline |
| 4071.50.052 | PRISM KEEPER PLATE | Spare will remain available after End of Support Deadline |
| 63A0986 | SEAL, PRISM KEEPER PLATE | Spare will remain available after End of Support Deadline |
| 4071.50.360 | PRISM CLAMP | Spare will remain available after End of Support Deadline |
| 4072.42.351 | CORD 2 CONDUCTOR | Spare will remain available after End of Support Deadline |
| 4072.42.380 | CORD CABLE CLAMP | Spare will remain available after End of Support Deadline |
| 44A7228/00101 | INTERM PAN PCB ASSY 50/60Hz,SNGL DRV,NM | Spare will remain available after End of Support Deadline |
| 44A7273/1 | POWER INTERFACE PCB LEAD LENGTH-1 | Spare will remain available after End of Support Deadline |
| 44A7387/10 | F-RANGE CORD SET OVERMOLD STYLE 1 | Spare will remain available after End of Support Deadline |
| 54A0022/8060 | THERMOSTAT, ARCTIC KIT | Spare will remain available after End of Support Deadline |
| 60A2602 | PRESSURE RELIEF SCREW | Spare will remain available after End of Support Deadline |
| 61A0459 | HEATER DISC, 2 LEADS W/Terminals | Spare will remain available after End of Support Deadline |
| 63A1285 | O-RING, INNER COVER SEAL | Spare will remain available after End of Support Deadline |
| 63B0267/011 | O-RING, PRESSURE RELEASE SCREW | Spare will remain available after End of Support Deadline |

| | | |
|----------------|--------------------------------------|---|
| 70A0329 | CORD SET TERMINAL, FEMALE DISCONNECT | Spare will remain available after End of Support Deadline |
| 72A0401 | ALUM GRND LUG, FOR AL/CU & UL467 | Spare will remain available after End of Support Deadline |
| MS00001-376-01 | O-RING, TOP INNER COVER | Spare will remain available after End of Support Deadline |

Last-Time Buy Conditions:

- All purchase orders for last -time buys are non-cancellable and non-returnable.
- For orders for only spare parts, a \$150 order minimum is required.
- Leadtime of the spare parts will be confirmed upon order confirmation
- During the final stage of a Spare Part Supply phase ADB Safegate can no longer guarantee full support for the affected products. Spare parts are provided depending on the available inventory; repair and replacement services also depend on component availability.



Appendix A:

BOTTOM PAN ASSEM., 1 CDST, L-852A/B, 1-2 LED's, W/O MON

