

Operation Manual

High Performance LED Light Bar Prod. No. 849840 Mod. No. JALB-2000

INSTRUCTIONS FOR USE

Your new Startech Under Hood Light is designed for use with or without its cord. For cordless use, plug charger into any 100 – 240 V AC power source and let the Lithium Ion battery charge until all 5 bars of the indicator illuminate. This may take 3-4 hours. Once charged, disconnect power cable from power source, then unscrew fitting on light to remove cord. Store cord in a safe place.

IF NOT IN CONTINUOUS USE, CHARGE BATTERY EVERY 3 MONTHS. For unlimited run time, leave power cable connected to light and power source.

OPERATION

- · Switch "I": 1000 Lumens
- · Switch "O": Off
- Switch "II": 2000 Lumens

Battery charge indicator shows state of charge at both 1000 and 2000 lumen settings

ATTACHING TO VEHICLE


Pull one padded hook out and hook on hood edge. While holding this hook firmly against hood, pull out second hook to grasp the other edge of the hood and allow hook to retract under firm control. Ensure both hooks are engaged before commencing work.


To aim light to provide best illumination rotate it along its axis. The clicking sound is produced by built in ratchets which will hold the light in position.


WARNINGS AND CAUTIONS


- Read and understand these instructions before use and retain for future reference
- · For indoor use only
- Risk of electric shock or spark. Do not operate in combustible or explosive environments
- · Do not use with wet hands
- · Keep out of reach of children
- · Do not look directly at light to avoid eye damage
- Do not use with damaged cord
- Always grasp plug, not cord, to disconnect from power source
- · Do not open, repair, or modify light

Warranty is one year from date of purchase by the end user and covers defective parts and workmanship only. Signs of misuse, alteration, or use with other than supplied power cord void warranty.











Low



