


## ENGINEERING CHANGE NOTICE

## Wiper Blade Change HP M252





Intl: +1.919.774.3808 | US, Toll-Free: 1.800.488.2426 | email: info@scc-inc.com | web: www.scc-inc.com



## ENGINEERING CHANGE NOTICE

Manufacturing location and packaging change. This can be referenced by the photographs shown above. This change does not affect product performance. Mixed shipments are possible. Affected Product Code & Starting Lot Numbers below:

Affected Product Code	Starting Lot Code
HM252WBLD-10	29042024-1

Intl: +1.919.774.3808 | US, Toll-Free: 1.800.488.2426 | email: info@scc-inc.com | web: www.scc-inc.com