

SYMBOL DEFINITION

A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL (1) DOES NOT REQUIRE INSPECTION; IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.	TOTAL NO. OF INSPECTIONS REQUIRED
LAST NO. USED	14

MISSED SYMBOLS

SPEC. DATE	DATE	REVISION HISTORY	APP'D	DWG NO.
2006/04/08	R	B1 - -	RELEASED	200604/14
2006/08/08	R	B2 - -	OKW #1 WAS 3.1	403016/NOI/AMV/MC/H

SECTION A-A

NOTES

- UNLESS OTHERWISE SPECIFIED AND/OR INDICATED:
DIMENSIONS ARE TO FACE OF VIEW SHOWN AND AUTOMATICALLY ROUNDED BY COMPUTER FOR INSPECTION (SEE MATH MODEL FOR PRECISE DIMENSIONS). FOR ALL OTHER DIMENSIONS NOT SHOWN BUT REQUIRED FOR TOOL BUILD, SEE MATH MODEL FOR PRECISE TOOL PATH DATA.
- THIS PART USED IN ASSEMBLY 13604604.
- REFERENCE MATING COMPONENTS OR EQUIVALENT: CONN 13604603.
- MATERIAL RECYCLING CODE PER ISO 11469, 111X(10,1) CHARACTERS AS SHOWN TO BE LOCATED ON ANY EXTERIOR SURFACE.