



①

G

--	--



①

A _____ LINE DRAWN THROUGH A PART NUMBER INDICATES THAT PHYSICAL PARTS ARE NOT AVAILABLE FOR ORDERING.

PART NUMBERS THAT DO NOT HAVE A LINE PRESENT INDICATE THAT PHYSICAL PARTS ARE AVAILABLE FOR ORDERING.

CONTACT ACTIV SALES TO ASSURE AVAILABILITY OF PARTS.



SHARP CORNER TOLERANCE

SCALE
1 : 1

• **A P T I V** •