Product Discontinuation Notice (PDN)



Ref No: PDN.LGT-HSIGN_GSF-HXXX.001

December 3, 2020

Dear Valued Customer,

This notice is to inform you that ADB Safegate has discontinued manufacturing of the **FAA L-858 AGSF** – **Incandescent Airfield Guidance Signs** as listed in the "Product Transition Table" included in this notification. The products contained in this notice are part of our annual product portfolio review process.

In accordance with ADB Safegate product discontinuation policy, we are hereby giving notice of these changes so that our customers and trusted partners can adjust their product purchasing records to support their operations.

Product Transition Table		
Product Name	FAA L-858 AGSF – Incandescent Airfield Guidance Signs	
Reason(s) for Discontinuance	Little to no demand, end-of-life (EOL) stage.	
Last time buy deadline	December 1, 2020	
	Orders will not be accepted after this date.	
End-of-Support deadline	December 1, 2025	
	Spare parts will no longer be available for warranty or non-warranty support, and technical support will be limited to fee-based repair work.	

Equivalent product replacements are available for this product as indicated in the "Product Replacement Table" below.

Product Replacement Table		
Discontinued Part Numbers	Replacement Part Number	
SHXX-XXXXXXX SWXX-XXXXXXX	L-858(L) AGSF-L LED Airfield Guidance Signs https://adbsafegate.com/product-center/airfield/?prod=agsf-l-l858- led-airfield-guidance-sign-faa	
	LED Retrofit Kits 94A0628/XX0 - Converts existing incandescent sign power supply and lamps to LED power supply and LED light bars.	

FAA Opinion on Mixing of Light Source Technologies – Per AC150/5340-30J paragraph 1.4

1.4 Signs Per Location - Do not collocate LED signs with incandescent signs. Example: runway holding position signs on both sides of a taxiway, holding position signs on both sides of a runway, separate signs that form a sign array.

It should be noted that for most applications it is permissible to mix LED and incandescent signs on an airfield. It is only prohibited to mix incandescent and LED signs where signs are placed side-by-side or in relation to each other as described in paragraph 1.4 "Examples". For these installations a cost-effective recommendation is to convert the incandescent signs to LED technology using LED Retrofit Kits 94A0628/XX0.

Rev: D Page 1 of 2

Product Discontinuation Notice (PDN)



Spare Parts

The table below shows spare parts that were available for the previously referenced product for a limited time. The list is based on common spare parts for this product, as shown in the manual or on the catalog sheet. While ADB Safegate will make every effort to maintain spare parts until the "End-of-Support" deadline, this will depend on the availability of older technology components. We highly encourage airports to stock an adequate quantity of recommended spare parts.

L-858 AGSF – Incandescent Airfield Guidance Signs			
Spare Part No	Description	Notes	
44A7199/200	Halogen Sign Power Supply Assembly	Spare Obsolete After End of Support Deadline	
60A2653	Lamp Cover	Spare Obsolete After End of Support Deadline	
63A0989	Lamp Cover Seal	Spare Obsolete After End of Support Deadline	
94A0373	Optional Lamps-Out Indicator Kit (Including Unique Sub-Components)	Spare Obsolete After End of Support Deadline	
2990.40.827	48W Halogen Lamp	Spare Not Intended to be Made Obsolete	
73A0107/72	Cord Set 72"	Spare Not Intended to be Made Obsolete	
62A2142	Standard Mounting Flange 2-Bolt	Spare Not Intended to be Made Obsolete	
62A2146	High-Wind Mounting Flange 4-Bolt	Spare Not Intended to be Made Obsolete	
60A2678/10	Frangible Coupling Size 1 Mode 2	Spare Not Intended to be Made Obsolete	
60A2678/20	Frangible Coupling Size 2 Mode 2	Spare Not Intended to be Made Obsolete	
60A2678/30	Frangible Coupling Size 3 & 5 Mode 2	Spare Not Intended to be Made Obsolete	
60A2678/40	Frangible Coupling Size 4 Mode 2	Spare Not Intended to be Made Obsolete	
60A2678/50	Frangible Coupling Size 1 Mode 3	Spare Not Intended to be Made Obsolete	
60A2678/11	Frangible Coupling Size 2 Mode 3	Spare Not Intended to be Made Obsolete	
60A2678/21	Frangible Coupling Size 3 Mode 3	Spare Not Intended to be Made Obsolete	
60A2678/31	Frangible Coupling Size 4 Mode 3	Spare Not Intended to be Made Obsolete	
60A2678/41	Frangible Coupling Size 5 Mode 3	Spare Not Intended to be Made Obsolete	

• For orders for spare parts, a \$150.00 order minimum is required.

We regret the inconvenience and impact this notice may cause. ADB Safegate Sales Representatives stand ready to answer any questions you may have or assist you with any final orders. Contact us at 1.800.545.4157.

Product Management Group



www.adbsafegate.com

Rev: D Page 2 of 2