

PRODUCT DISCONTINUATION NOTICE AD-lights DTS/DTC Low Protrusion (Style III)





Product Support Change Notice

Dear Valued Customer,

This notice is to inform you that ADB SAFEGATE has discontinued the sourcing and supplying of all fittings and several spare parts listed in this notice from the **DTC/DTS LP**, style III inset **Taxiway Centerline and Stop Bar** family.

In accordance with ADB SAFEGATE product discontinuation policy, we are hereby giving notice of these changes so that our customers can adjust their product part number purchasing records or make any final lifetime purchases of spare parts to support their operations.

Our portfolio of style III fittings has evolved and currently AXON-range can be offered using the most modern LEDs-engines enabling highly efficient light output and long operational lifetime. Remarkably, our engineering department has worked on upgrading the design of the DTC/DTS LP light engines using updated LP2-family light engines which is effectively enabling extending the lifecycle of the DTC/DTS LP installed base. Light engines and top covers of the DTC/DTS LP family will be catered using the upgraded spare parts according to the spare parts scheme attached in this notice. Consequently, if a light engine of DTC/DTS LP will need to be replaced, the complete top cover assembly and updated light engines will need to be ordered. Please familiarize yourself with the new replacement parts scheme and update your purchasing records.

In this notice below you can also find the necessary details about the successor product, updated spare parts, and last time buy conditions.

We regret the inconvenience and impact this notice may cause. ADB Safegate Sales Representatives stand ready to answer any questions you may have or assist you with any final orders or alternative solutions.

> ADB SAFEGATE Rikard LARSSON Product Management Team







Discontinuation Planning

Product Name	DTC/DTS LP - inset Taxiway Centerline and Stop Bar
Reason(s) for Discontinuance	Parts obsolescence.
Last time buy deadline	31 December 2019
	The last time buy deadline has passed. ADB Safegate is not supplying new fittings anymore.
End-of-Support deadline	31 December 2024
	Spare parts support stage is offered for the selected spare parts. The change in the availability is listed below.
	Customers are strongly advised to replenish their stock of key spare parts before 31 December 2024.
	Spare parts are subject to availability. In case of spare parts including an obsolete component, the ADB SAFEGATE sales representative shall assist providing a solution based on replacement products, listed below.

Replacement Product

Discontinued Part Numbers	Replacement Part Numbers
DTC/S LP (style III) Order codes fitting to the key: <i>DTxxxxxBxxxxx</i>	AXON Taxiway Centerline and Stopbar lights (Style III) https://adbsafegate.com/products/airfield/taxiway- lighting/axon-led-taxiway-centerline-icao https://adbsafegate.com/products/airfield/taxiway- lighting/axon-led-stop-bar-8-12-ICAO Order codes fitting to the following keys: • RSTK*1 • RSTW*1 • RSSB*1



Spare Parts Availability

Due to obsolescence, if a light engine or a top cover of DTC/DTS LP will need to be replaced, the complete top cover assembly and updated light engines will need to be ordered.

Spare Part Number	Spare Part Description
SP.013189	DTS LP2, TOP CVR ASSY, 8" Uni, win 1
SP.013190	DTC LP2,TOP CVR ASSY,8" Uni,win 1
SP.013191	DTS LP2, TOP CVR ASSY, 8" Uni, win 2
SP.013192	DTC LP2,TOP CVR ASSY,8" Uni,win 2
SP.013193	DTS LP2,TOP CVR ASSY,8" Bidir
SP.013194	DTC LP2,TOP CVR ASSY,8" Bidir
SP.013195	DTS LP2,TOP CVR ASSY,8" Uni,win 1,SAP
SP.013196	DTC LP2,TOP CVR ASSY,8" Uni,win 1,SAP
SP.013197	DTS LP2,TOP CVR ASSY,8" Uni,win 2,SAP
SP.013198	DTC LP2,TOP CVR ASSY,8" Uni,win 2,SAP
SP.013199	DTS LP2,TOP CVR ASSY, 8" Bidir,SAP
SP.013200	DTC LP2,TOP CVR ASSY, 8" Bidir,SAP
SP.013223	DTS LP2,TOP CVR ASSY,8" Uni,win 1,CN
SP.013224	DTC LP2,TOP CVR ASSY,8" Uni,win 1,CN
SP.013225	DTS LP2,TOP CVR ASSY,8" Uni,win 2,CN
SP.013226	DTC LP2,TOP CVR ASSY,8" Uni,win 2,CN
SP.013227	DTS LP2,TOP CVR ASSY,8" Bidir,CN
SP.013228	DTC LP2,TOP CVR ASSY,8" Bidir,CN
SP.013229	DTS LP2,TOP CVR ASSY,8" Uni,win 1,SAP,CN
SP.013230	DTC LP2,TOP CVR ASSY,8" Uni,win 1,SAP,CN
SP.013231	DTS LP2,TOP CVR ASSY,8" Uni,win 2,SAP,CN
SP.013232	DTC LP2,TOP CVR ASSY,8" Uni,win 2,SAP,CN
SP.013233	DTS LP2,TOP CVR ASSY, 8" Bidir,SAP,CN
SP.013234	DTC LP2,TOP CVR ASSY, 8" Bidir,SAP,CN
SP.013201	DTS LP2, Optical ASSY, Red
SP.013202	DTC LP2, Optical ASSY, Red
SP.013203	DTS LP2, Optical ASSY, Green
SP.013204	DTC LP2, Optical ASSY, Green
SP.013205	DTS LP2, Optical ASSY, Yellow
SP.013206	DTC LP2, Optical ASSY, Yellow

* CN – anodized top cover

** SAP – sapphire-protected prism

Please notice that this list is not including all available spare parts but represents an addendum to the spare parts list provided before.



Last-Time Buy Conditions:

- All purchase orders for last -time buys are non-cancellable and non-returnable.
- For orders for only spare parts, a €150 order minimum is required.
- Leadtime of the spare parts will be confirmed upon order confirmation.
- During the final stage of a Spare Part Supply phase ADB Safegate can no longer guarantee full support for the affected products. Spare parts are provided depending on the available inventory; repair and replacement services also depend on component availability.

